U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

P/N 28-AD-0019

DAM 2091

Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)							
		SEC1	TION I				
MANUFACTURER'S NAME				EMERGENCY	/ TEL EBHONE		
Essex Chemical Corp. Coast Pro-Seal Division (213) 636-0851							
ADDRESS (Number, Street, City, State, and ZIP Co 19451 Susana Road, Compt	dal			(213) (<u> </u>	<u>L</u>	·····
I CHEMICAL NAME AND SYNONYMS			TRABENIAL	ME AND SYN	ONYMS		 -
Adhesive MYLAR W/Accelerator I CHEMICAL FAMILY N/A	: NO	اد بنظناد.	FORMULA ACCE.	lerator	<u>:</u>		
N/A		 -	N/A				
SECTION	11 -	HAZAF	RDOUS INGREDIEN	NTS			
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS			%	TLV (Units)
PIGMENTS			BASE METAL				
catalyst Organic Peroxide	20	-25%	ALLOYS			-	
VEHICLE Epoxy resins	75	80%	METALLIC COATINGS	-			
SOLVENTS			FILLER METAL PLUS COATING OR CO	PF FI UX		 	
ADDITIVES			OTHERS	NET LOX			_
OTHERS							
HAZARDOUS MIXTURES	OF (DTHER LIC	DUIDS SOLEDS OR GASE	Ee		9/	TLV
	<u> </u>					%	(Units)
							
							
SEC ⁻	TIOI	VIII - P	HYSICAL DATA				
BOILING POINT (°F.)		N/A	SPECIFIC GRAVITY (H2	O=1)		ļ	1
VAPOR PRESSURE (mm Hg.) N/A		PERCENT, VOLATILE BY VOLUME (%)			0		
VAPOR DENSITY (AIR=1) N/A		EVAPORATION RATE (=1)		N	/A		
SOLUBILITY IN WATER		Nil					
APPEARANCE AND ODOR VISCOUS CL	ear	liqui	id - faintly s	sweet c	odor		
SECTION IV - I	FIRE		XPLOSION HAZAR				
FLASH POINT (Method used) Over 200 deg. F open cup FLAMMABLE LIMITS Lel Uei						Uel	
EXTINGUISHING MEDIA Dry chemica.		CO ₂ , f	oam, water		ī		
SPECIAL FIRE FIGHTING PROCEDURES NOT							
UNUSUAL FIRE AND EXPLOSION HAZARDS	one						

PAGE (1)

SECTION V - HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE UNKNOWN EFFECTS OF OVEREXPOSURE	·
May cause irritation of skin or mucous memb	ranes
EMERGENCY AND FIRST AID PROCEDURES	
Flush throughy with water, soap if s If accidently ingested, give emetic and consult physician.	kin.
The test of the second	

			SECTION	ON VI - F	REACTIVITY DATA
STABILITY UNSTABLE STABLE INCOMPATABILITY (Materials to avoid)		CONDITIONS TO AVOID			
			х	Hig	Jh temperature.
HAZARDOUS DE		•	Avo		ong reducing agents.
		TON PRODUC	Co		
HAZARDOUS POLYMERIZATION		MAY OCCUR	MAY OCCUR		CONDITIONS TO AVOID
		WILL NOT OCCUR		х	

SEC	TION VIII COUL OR LEAVE -
STEPS TO BE TAKE	CTION VII - SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CASE MATE	RIAL IS RELEASED OR SPILLED
01.0	
crean up spillage wit	h rags or sweeping compound and solvents.
	z j simpound and solvents.
WASTE DISPOSAL METHOD	
Pr	eferably burn waste.
-	
·	

	SECTION VIII SPECIAL E		
RESPIRATORY DO	SECTION VIII - SPECIAL P	PROTECTION INFORMATION	
N-S/MATORY PR	COTECTION (Specify type)		
VENTILATION	Recimended	d areas, cannister type	
220	MECHANICAL (General)	OTHER	
PROTECTIVE GLOVES Recommended OTHER PROTECTIVE EQUIPMENT		EYE PROTECTION Recommended	
OTHER PROTECTI	~	rons	

SECTION	NIX - SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN IN HANDLING AN	ID STORING AVOID CORT and investigation
below 80 deg. F	Avoid contact and ingestion. Store
OTHER PRECAUTIONS None	

PAGE (2)

GPO 934-110

Form OSHA-20 Rev. May 72